

M/Y "MR. LOUI"

SUN DECK



• CONTINUED WITH POLISH AND REPAIR DETAILS OF PAINT ON SUN DECK (BAR TABLE, BARBECUE TABLE, DOORS AND ACCESSORIES).



CONTINUE WITH DETAILS ON TEAK DECK.



• THE STAINLESS STEEL TABLE AND THE TEMPERED GLASS OF LATERAL BARS (PS AND SB) WERE RECEIVED.



UPPER DECK





M/Y "MR. LOUI"

• FRIGOBAR AND ICE MAKER WERE RECEIVED AND INSTALLED.



• CARPENTRY JOBS CONTINUED IN THE SKY SALON, START TO INSTALL ROOF CELING AND TESTING LIGHTS.



• IT FINISHED INSTALLING FLOOR IN SKY SALON.



START CARPENTRY JOBS IN LOBBY.



• CARPENTRY JOBS CONTINUE ON PILOT HOUSE.





M/Y "MR. LOUI"

CONTINUE WITH INSTALLATION OF PUMPS AND PVC PIPES ON JACUZZI.



• BOTH SIDES MR LOUI NAMES WERE MOUNTED.



MAIN DECK



CONTINUE WITH REPAINT AND FIX DETAILS ON AFT DECK.



• CONTINUE WITH INSTALLATION OF TV AND AUDIO RACK, ON THE GALLEY.



• START CARPENTRY JOBS ON SB LOBBY.



M/Y "MR. LOUI"



THE AFT MR LOUI NAME WAS MOUNTED.









LOWER DECK



CONTINUE WITH CARPENTRY JOBS IN VIP LOBBY.



• ALL EMERGENCY STEEL WINDOWS WERE INSTALLED.





M/Y "MR. LOUI"



CREW CABINS

CONTINUE WITH CARPENTRY JOBS.



CREW MESS

CONTINUE WITH CARPENTRY JOBS. THE DIMENTIONS OF THE SEAT WERE FIX IT.



CONTINUE WTH CARPENTRY JOBS ON STAIRS TO CREW DECK.



ENGINE ROOM

• CONTINUE TO INSTALLING ROOF CELING.



Página 5 de 7





• ALL LED LIGHTS WERE INSTALLED.



• MAIN ENGINE COOLANT DEPOSITS WERE INSTALLED.



• 3000 LTS. OF MARINE GAS OIL WAS RECEIVED.



HULL AND PROPULTION

• BOTH SIDES SHAFT SEAL PROTECTIONS PLATES, WERE RECEIVED AND PAINTED.





M/Y "MR. LOUI"

• ALL ZINC ANODES WERE INSTALLED ON HULL BOTTOM.



• ALL HULL BOTTOM WAS PAINTED.

